

# DOOR SOLUTIONS

**Problem:**

Leaking door lite frame.

**Cause:**


Often caused by lack of overhang and direct sunlight, or chemicals used on glass during construction.

**Solution:**

Order replacement door lite frame.



**RECOMMENDED OVERHANG**



The "Projection of Overhang" must measure a minimum of 1/2 the height of the entryway. The "Side of Overhang" must measure a minimum of three feet from the outside edge of the door unit. The overhang must provide protection of the door unit from direct exposure to the elements.

